

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd. Wood Village, OR 97060 (503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description					
2011 Chevrolet G3500 Vans Flex Ext Wagon Express					
VIN	1GAZG1F	1GAZG1FG6B1150178			
Ext. Color	Gold	Gold			
Int. Color	Tan	Interior Cloth			
Mileage	82,016 Ac	82,016 Actual Miles			
Engine	6.0L 8-Cyl	6.0L 8-Cylinder Gas			
Transmission	Automatic	Automatic			



Auction Data				Declarations		
Sale Date	Mon - Feb 8	- Open to the Public	Warranty	GSA Regular Terms		
Run#	W026	Inv # 8638	Mileage	82,016 Actual Miles		
Consignor	GSA FLEET	SERVICES	Title	Clear Title		

Equipment

- 2 Wheel Drive
- · Air Conditioning

Electric Mirrors

- Cruise Control
- AM/FM CD
- AIVI/FIVI CD
- Automatic Transmission
- Power Windows
- Dual Air Bag
- Hard Top

- 8 Cylinder Gas
- Power Locks
- · Alloy Wheels
- Power Steering
- 12 Passenger
- Trip Counter
- · Tilt Steering Wheel
- Power Brakes

			Damage	e Descriptions (CR	completed on	12/30/2015	by LUIS M	1EJIA)		
	#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front	1	Hood	Chipped	Multiple Instances						
				Front Subtotal						
Interio	2	Steering Wheel	Worn	Acceptable						

2011 Chevrolet G3500 Vans Flex Ext Wagon Express

VIN: 1GAZG1FG6B1150178 **Inv#:** 8638

	cceptable Left Subtotal		-	 		-	
aht Scratch Mi	Left Subtotal					-	
aht Scratch Mi						<u></u>	
giit Sciatori Mi	ultiple Instances						
	Rear Subtotal		-				
ght Scratch M	ultiple Instances						_
ght Scratch M	ultiple Instances						
ī	Right Subtotal	-	-				
	Total						
ç	ght Scratch M ght Scratch M	Rear Subtotal ght Scratch Multiple Instances ght Scratch Multiple Instances Right Subtotal	Rear Subtotal ght Scratch Multiple Instances ght Scratch Multiple Instances Right Subtotal	Rear Subtotal ght Scratch Multiple Instances ght Scratch Multiple Instances Right Subtotal	Rear Subtotal	Rear Subtotal	Rear Subtotal

Tires				
Region	Brand	Size	Tread Depth	
Left Front	MATCHED	/-	Average (Average)	
Left Rear	MATCHED	/-	Average (Average)	
Right Front	MATCHED	/-	Average (Average)	
Right Rear	MATCHED	/-	Average (Average)	
Spare	FACTORY	/-	Average (Average)	

		Miscellaneous
Coolant level	OK	
Interior odor	OK	
Oil level	OK	
Transmission fluid level	OK	

2011 Chevrolet G3500 Vans Flex Ext Wagon Express

VIN: 1GAZG1FG6B1150178 Inv#: 8638



2011 Chevrolet G3500 Vans Flex Ext Wagon Express

VIN: 1GAZG1FG6B1150178 **Inv#:** 8638



